

Appendix B

Images from an 'all walls out' woolaway refurbishment. This is a comprehensive renewal of the building and home.

b: "Walls Out" Refurbishment
of PRC Woolaway houses
Illustrations of the construction method

Job No: 080231 Photosheet No: Page 1 of 3

Date : Dec 2021



P1 – Excavation for foundation extension



P2 – New drainage



P3 – New drainage



P4 – Dowel bars into existing foundations



P5 – Staircase running parallel to the front wall (see also P9).



P6 – First floor propping with vertical support to roof rafter



P7 – Ground floor propping (prior to erection of security screening)



P8 – Ground floor propping (prior to erection of security screening)



P9 – Propping on stairs (security screen at ground floor, first floor to be erected)



P10 – Demolition



P11 – Demolition



P12 – External Walls